

The Multivolt Box has been fixed




FBI alignment on Control Camera (IMAGES)

IMAGES SPOTS BEFORE ALIGNMENT




IMAGES SPOTS AFTER ALIGNMENT






FBI alignment on Control Camera (PUPILS)

PUPILS AFTER ALIGNMENT




We have installed LED lights under the cover

INJECTION TABLE



SPECTRO TABLE



THE TEAM

